

## Specifications

### OCSA/B/C/M/L

Model	OCSA	OCSB	OCSC	OCSM	OCSL
Panel Button	Water-proof	Water-proof	Water-proof	Water-proof	Water-proof
Zero	Yes	Yes	Yes	Yes	Yes
Tare In / Tare Out	Yes	Yes	Yes	Yes	Yes
Hold	Yes	Yes	Yes	Yes	Yes
Low Voltage Alarm	Yes	Yes	Yes	Yes	
Battery Supervision	Yes	Yes	Yes	Yes	Yes
Overload Alarm / Record	Yes	Yes	Yes	Yes	
Digital Calibration	Yes	Yes	Yes	Yes	Yes
3-point Linearity Correction	Yes	Yes	Yes	Yes	Yes
Unit switch	kg/lb	kg/lb	kg/lb	kg/lb	kg/lb/N
Gravity Acceleration Set	Yes	Yes	Yes	Yes	
Tare Set	Yes	Yes	Yes	Yes	
Total / Delete / Clear Total	Yes	Yes	Yes	Yes	
View Total	Yes	Yes	Yes	Yes	
Resolution Switch	Yes	Yes	Yes	Yes	
Auto-off Set	Yes	Yes	Yes	Yes	Yes
Idle Set	Yes	Yes	Yes	Yes	3 sec
Display Luminance Set	Yes	Yes	Yes	Yes	
Display Speed Set	Yes	Yes	Yes	Yes	
Anti-motion Set	Yes	Yes	Yes	Yes	
Tare Range	100% F.S.	100% F.S.	100% F.S.	100% F.S.	100% F.S.
Zero Range	4% F.S.	4% F.S.	4% F.S.	4% F.S.	4% F.S.
Save Overload	120% F.S.	120% F.S.	120% F.S.	120% F.S.	120% F.S.
Ultimate Overload	400% F.S.	400% F.S.	400% F.S.	300% F.S.	300% F.S.
Overload Alarm	100% F.S. +9e	100% F.S. +9e	100% F.S. +9e	100% F.S. +9e	100% F.S. +9e
Battery	6V/10Ah	6V/10Ah	2 X 6V/3.2Ah	6V/5Ah	3 x 1.5V AA
Power Adapter	9V/1500mA	9V/1500mA	9V/1000mA	9V/1500mA	N/A
Effective Remote Distance	10 meter / 32.8 feet	10 meter / 32.8 feet	10 meter / 32.8 feet	10 meter / 32.8 feet	N/A
Operation Temperature Range	-10°C ~40°C 14°F~104°F	-10°C ~40°C 14°F~104°F	-10°C ~40°C 14°F~104°F	-10°C ~40°C 14°F~104°F	-10°C ~40°C 14°F~104°F