

Specifications

OCSG/Z/T/S/D

Model	OCSG	OCSZ	OCST	OCSS	OCSD
Panel Button	Stainless Steel	Stainless Steel	Water-proof	Water-proof	
Zero	Yes	Yes	Yes	Yes	Yes
Tare In / Tare Out	Yes	Yes	Yes	Yes	Yes
Hold	Yes	Yes	Yes	Yes	Peak Hold
Low Voltage Alarm	Yes	Yes	Yes	Yes	Yes
Battery Supervision	Yes	Yes	Yes	Yes	Yes
Overload Alarm / Record	Yes	Yes	Yes	Alarm Only	2 Alarm Set-Point
Digital Calibration	Yes	Yes	Yes	Yes	Yes
3-point Linearity Correction	Yes	Yes	Yes	Yes	Yes
Unit switch	kg/lb	kg/lb	kg/lb	kg/lb	kg/t/lb/N/kN
Gravity Acceleration Set	Yes	Yes	Yes	Yes	Yes
Tare Set	Yes	Yes			Yes
Total / Delete / Clear Total	Yes	Yes	Yes		Yes
View Total	Yes	Yes	Yes		Yes
Resolution Switch	Yes	Yes	Yes	Yes	Yes
Auto-off Set	Yes	Yes	Yes	Yes	Yes
Idle Set	No	No	Yes	Yes	Yes
Display Luminance Set	No	No	Yes	Yes	Yes
Display Speed Set	Yes	Yes			Yes
Anti-motion Set	Yes			Yes	Yes
Tare Range	100% F.S.	100% F.S.	100% F.S.	100% F.S.	100% F.S.
Zero Range	4% F.S.	4% F.S.	4% F.S.	4% F.S.	4% F.S.
Save Overload	120% F.S.	120% F.S.	120% F.S.	120% F.S.	120% F.S.
Ultimate Overload	500% F.S.	500% F.S.	400% F.S.	400% F.S.	400% F.S.
Overload Alarm	100% F.S. +9e	100% F.S. +9e	100% F.S. +9e	100% F.S. +9e	2 Alarm Set-Point
Battery	6V/10Ah	6V/10Ah	6V/4Ah	3 X AA	3 X AA
Power Adapter	9V/1500mA	9V/1500mA	7.2V/1000mA	N/A	N/A
Effective Remote Distance	10 meter / 32.8 feet	10 meter / 32.8 feet	10 meter / 32.8 feet	N/A	N/A
Operation Temperature Range	1000°C =>1200mm 1600°C =>2000mm	-10°C ~40°C 14°F~104°F	-10°C ~40°C 14°F~104°F	-10°C ~40°C 14°F~104°F	-20°C ~50°C -4°F~122°F