

Specifications

OCSG/Z/T/S/D

| Model | OCSG | OCSZ | OCST | OCSS | OCSD |
|------------------------------|------------------------------------|---------------------------|---------------------------|---------------------------|---------------------------|
| Panel Button | Stainless Steel | Stainless Steel | Water-proof | Water-proof | |
| Zero | Yes | Yes | Yes | Yes | Yes |
| Tare In / Tare Out | Yes | Yes | Yes | Yes | Yes |
| Hold | Yes | Yes | Yes | Yes | Peak Hold |
| Low Voltage Alarm | Yes | Yes | Yes | Yes | Yes |
| Battery Supervision | Yes | Yes | Yes | Yes | Yes |
| Overload Alarm / Record | Yes | Yes | Yes | Alarm Only | 2 Alarm Set-Point |
| Digital Calibration | Yes | Yes | Yes | Yes | Yes |
| 3-point Linearity Correction | Yes | Yes | Yes | Yes | Yes |
| Unit switch | kg/lb | kg/lb | kg/lb | kg/lb | kg/t/lb/N/kN |
| Gravity Acceleration Set | Yes | Yes | Yes | Yes | Yes |
| Tare Set | Yes | Yes | | | Yes |
| Total / Delete / Clear Total | Yes | Yes | Yes | | Yes |
| View Total | Yes | Yes | Yes | | Yes |
| Resolution Switch | Yes | Yes | Yes | Yes | Yes |
| Auto-off Set | Yes | Yes | Yes | Yes | Yes |
| Idle Set | No | No | Yes | Yes | Yes |
| Display Luminance Set | No | No | Yes | Yes | Yes |
| Display Speed Set | Yes | Yes | | | Yes |
| Anti-motion Set | Yes | | | Yes | Yes |
| Tare Range | 100% F.S. | 100% F.S. | 100% F.S. | 100% F.S. | 100% F.S. |
| Zero Range | 4% F.S. | 4% F.S. | 4% F.S. | 4% F.S. | 4% F.S. |
| Save Overload | 120% F.S. | 120% F.S. | 120% F.S. | 120% F.S. | 120% F.S. |
| Ultimate Overload | 500% F.S. | 500% F.S. | 400% F.S. | 400% F.S. | 400% F.S. |
| Overload Alarm | 100% F.S. +9e | 100% F.S. +9e | 100% F.S. +9e | 100% F.S. +9e | 2 Alarm Set-Point |
| Battery | 6V/10Ah | 6V/10Ah | 6V/4Ah | 3 X AA | 3 X AA |
| Power Adapter | 9V/1500mA | 9V/1500mA | 7.2V/1000mA | N/A | N/A |
| Effective Remote Distance | 10 meter / 32.8 feet | 10 meter / 32.8 feet | 10 meter / 32.8 feet | N/A | N/A |
| Operation Temperature Range | 1000°C =>1200mm 1600°C =>2000mm | -10°C ~40°C 14°F~104°F | -10°C ~40°C 14°F~104°F | -10°C ~40°C 14°F~104°F | -20°C ~50°C -4°F~122°F |